Annexure-D

BUILDING SAFETY CERTIFICATE

No. 2159 Dated-12-08-2026

It is certified that the existing building Samrat Vikramditiya Vidhyalay, Bagwara [run by Sarswati Vidhiya Pratisthan M.P. Bhopal] NH - 46, Village-Bagwara, Tehsil Budhni, District Sehore, Madhya Pradesh is having block (s) as per details below.

Detail of Block (s) in school	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)
No of Floor (s) in the	G	G	G	G	G

The building is owned/occupied by Samrat Vikramditiya Vidhyalay, Bagwara [run by Sarswati Vidhiya Pratisthan M.P. Bhopal] NH - 46, Village-Bagwara, Tehsil Budhni, District Sehore, Madhya Pradesh have complied with the Building safety requirements in accordance with National Building code Rules. and verified by the officers concerned of S.L. Rohitas S.D.O. PWD Budhni (Name of Department / Govt.) on 22-08-2026 (date of inspection) in the presence of Shri Mohan lal Gupta, Manager Samrat Vikramditiya Vidhyalay, Bagwara, Tehsil Budhni, District Sehore, (name and addresses of the manager/secretary or his representative) and that the building/premises is fit for occupancy of running school with effect from 22-08-2026 for a period of 05 years in accordance with rule and subject to compliance of the specific conditions as appended.

1. Class rooms and floors of the building are well maintained.

2. Drinking water facilities along are at each floor.

3. Electrical, Plumbing and Sanitary Line are perfect.

4. Overall Structural Condition is Very Good.

Issued on 22-08-2026 at Budhni by S.D.O. PWD Shri S. L. Rohitas

S. Rohitas

कार्यालय अनुविभागीय अधिकारी
लो. नि. वि. उपसंभाग क्र.02 बुदनी

Signature with Seal:
SUB Division P.W.D. Budhni

Name & Address of office: PWD Budhni

R.B. CHOUHAN
SUB ENGINEER
P.W.D.
Budhni